

VOLVO LAP Function List (Note:For reference only)

NOTES:

● This function is supported.

※ This function may be supported, which depends on the actual condition of the vehicle.

○ This function is not supported.

▲ This function is the new feature in this version.

Model	Model	Year	LAP
C30		2007	●
C30		2008	●
C30		2009	●
C30		2010	●
C30		2011	●
C30		2012	●
C30		2013	●
C70		2006	●
C70		2007	●
C70		2008	●
C70		2009	●
C70		2010	●
C70		2011	●
C70		2012	●
C70		2013	●
S40		2004.05 -	●
S40		2005	●
S40		2006	●
S40		2007	●
S40		2008	●
S40		2009	●
S40		2010	●
S40		2011	●
S40		2012	●
S60		2001	●
S60		2002	●
S60		2003	●
S60		2004	●
S60		2005	●
S60		2006	●
S60		2007	●
S60		2008	●
S60		2009	●
S60		2010	●
S80		1999	●
S80		2000	●
S80		2001	●
S80		2002	●
S80		2003	●
S80		2004	●
S80		2005	●
S80		2006	●

V50	2004	●
V50	2005	●
V50	2006	●
V50	2007	●
V50	2008	●
V50	2009	●
V50	2010	●
V50	2011	●
V50	2012	●
V70	2000.05 -	●
V70	2001	●
V70	2002	●
V70	2003	●
V70	2004	●
V70	2005	●
V70	2006	●
V70	2007	●
V70	-2008.05	●
XC70	2001	●
XC70	2002	●
XC70	2003	●
XC70	2004	●
XC70	2005	●
XC70	2006	●
XC70	2007	●
XC90	2003	●
XC90	2004	●
XC90	2005	●
XC90	2006	●
XC90	2007	●
XC90	2008	●
XC90	2009	●
XC90	2010	●
XC90	2011	●
XC90	2012	●
XC90	2013	●
XC90	2014	●
XC90	2015	●
XC90	2016	●

LAP Function List

Calibrating The Position Sensor For Bi-Xenon Lamps

Calibration Of Position Sensor, GDL Lamps

Position Sensor Xenon Lamp